

Technical drawing of a circular mechanical part, likely a flange or end view of a shaft component. The drawing shows concentric circles and radial lines indicating dimensions and radii.

Dimensions and Radii:

- Overall outer diameter: 150 (indicated by 75 on the left and 75 on the right).
- Inner diameter: 50 (indicated by 25 on the left and 25 on the right).
- Radius of the outermost circular feature: R65 (indicated by a dashed line and arrow).
- Radius of the innermost circular feature: R48 (indicated by a dashed line and arrow).
- Radius of the intermediate circular feature: R55 (indicated by a dashed line and arrow).
- Horizontal distance from the center to the start of the outermost feature: 45 (indicated by a dimension line).
- Horizontal distance from the center to the start of the innermost feature: 75 (indicated by a dimension line).
- Vertical distance from the center to the start of the outermost feature: 75 (indicated by a dimension line).
- Vertical distance from the center to the start of the innermost feature: 55 (indicated by a dimension line).

SCALE 1/2

SCALE 1/2

SCALE 1/2