

Top view of a mechanical part. The drawing shows concentric circles and radial lines. Key features include:

- Radial lines labeled **R95** and **R72**.
- Points labeled **P024** at the intersections of the radial lines and the circles.
- A scale indicator at the bottom right: **SCALE 1/3**.

