







1. 프로젝트 파일 없음
2. 본체(기준부품) 부품 미고정




1. 조립 오류




1. 조립 간섭




1. 도면 SR120은 외부 호의 치수
2. 도면 중심선






1. SR120



1. 모깍기



1. 구멍 피처 오류

1. 스케치 구속조건

