






1. 조립 오류 3점





2. 본체 스케치구속조건(26개소) 52점





2. 본체 스케치구속조건(26개소) 52점



2. 본체 스케치구속조건(26개소) 52점



2. 본체 스케치구속조건(26개소) 52점



2. 본체 스케치구속조건(26개소) 52점

